



Convert: 100
JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: August 3, 2009

Reviewed: JK

Mine Name: Daggett County Clay Pit	Permit Number: S/009/0004
Operator Name: Daggett County	Inspection Date: July 29, 2009
Inspector(s): L Heppler	Time: 9:00 am
Other Participants: none	Mine Status: Ina

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: No Bond held **Bond Amount:** \$0 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was inspected as a small mine site on 03/23/2006

Inspection Summary: Every effort should be made to salvage topsoil from the site prior to mining. There is no topsoil storage at any of these sites. Multiple disturbances were noted. Photos were taken to document site conditions.

Conclusions and Recommendations: There is no bond posted for these sites. Operator should either bond for the total disturbance on the ground or reclaim the areas that are mined out and bond for one working face at a time. Operator has 30 days to comply with all local, state and federal rules. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: James Olson

SITLA - Jblake@utah.gov

O:\M009-Daggett\S0090004-DaggettCountyClayPit\inspections\Insp-07292009.doc



West prospects



East Pit



Main Pit



Main Pit